

1/7




FIG. 1




FIG. 2

2/7




FIG. 3




FIG. 4

3/7




FIG. 5






FIG. 6



5/7

LOCATE THE UPPER AND LOWER WIRES:



\* - if required mandibular distalization > 4mm then  
 molar movement is not possible

FIG. 7B

6/7




FIG. 8




FIG. 9

7/7




FIG. 10




FIG. 11